


HEADS UP

CRUSH ZONES AND PINCH POINTS



IDENTIFIED HAZARDS

OVERHEAD CRANES can crush or injure. Stay out from under suspended loads and proceed with caution when safe to do so. Stay alert for **“THE BIGHT”** and keep your eyes on the task. Ensure your hands and feet are clear of any pinch points.



SAFE WORK PRACTICES

- Wear all required personal protective equipment
- Pay attention - Never turn your back when cargo is being lifted
- Move to a safe location – DO NOT STAND IN THE BIGHT
- Watch for pinch points and low clearance areas
- Work together with your partner and be aware of what your partner is doing
- Be aware of your surroundings at all times and avoid rushing

SAFETY IS EVERYONES RESPONSIBILITY. AN INJURY TO ONE IS AN INJURY TO ALL.