

# SAFETY ALERT

## Two Workers Injured When Jumping In Cargo Holds

### WHAT HAPPENED?



#### 1. LOWER LEG INJURY:

Worker tried to jump from one unit of pulp to another and hyperextended his leg.

#### 2. RIGHT ANKLE INJURY:

Worker jumped down approximately 3 feet from the top of the deck onto steel pipe and twisted his ankle.



**Both of these injuries were a result of jumping**

### SAFE WORK PRACTICES:

- A portable ladder **MUST** be used for access into hatches, if the ship access ladder is not available.
- Do not jump in cargo holds or onto uneven surfaces.