

# SAFETY ALERT

## Seat Belts

### WHAT HAPPENED:

A surf truck was reversing out of a van with 8 pulp bales when the bottom of the surf hit the steel ramp, causing the machine to suddenly stop. The rear end of the truck lifted, due to shifting pulp, then landed back on its rear wheels.



The driver required medical attention and lost time from work.

The driver was wearing his seatbelt, potentially preventing more serious injuries.

### SAFE WORK PRACTICES:

Raise the surf blade to an adequate height to clear the ramp.



Wear your seat belt.

**SAFETY IS EVERYONE'S RESPONSIBILITY**

<https://sharepoint.westeve.com>