

SAFETY ALERT

ARM CRUSH INJURY

WHAT HAPPENED :

Workers arm and wrist was crushed when arm was placed underneath frame

ACTIONS TO PREVENT RECURRANCE :

- Workers should be mindful of other operations on vessel which could cause listing of vessel
- Longer chains on each hook can reduce the risk of recurrence
- Reconfiguring the design of the legs on single wide frames

