

# SAFETY ALERT

## CARGO HOOK—SECURITY WIRE

### WHAT HAPPENED :

The spring loaded keeper which prevents wires from coming off the cargo hook was not working correctly, and the angle of the hook allowed the keeper to open—causing wire to come out.

### ACTIONS TO PREVENT RECCURANCE :

- All keepers were inspected with security wire placed between bridals and cargo hook shackle

### OTHER ACTIONS TO BE TAKEN:

- Review topside training to ensure they are checking keepers during initial inspection
- Ensure all supervisors are aware that there is a security wire between wire grommet (bridal) and the shackle when clasp is not working as intended

