

Lift Truck Struck Warehouse Post



WHAT HAPPENED:

While driving into A Alley in Warehouse 1, the driver cut the corner and stabbed the supporting pole with the left tine of the lift truck.

SAFE WORK PRACTICES:

- Do not drive through empty bins
- Do not take short cuts around edges of empty bins
- Stay on designated driving routes through the warehouse

MAKE SAFETY A HABIT